




1




2



3



4



(For United Kingdom only)  
**BE SURE TO READ THE CAUTION FOR THE AC MAINS LEAD ON PAGE 3 BEFORE CONNECTION.**

The battery takes 12 hours to fully charge.  
 Before connection to other components, follow steps **1** to **4** so that the battery starts charging immediately.

Ensure [MAIN POWER] is off when installing or removing the battery.

- 1** Insert the plug of the battery into the jack inside the battery compartment.

#### To disconnect the plug

Lift the lever and pull.


- 2** Put the battery into the compartment and attach the case with the two screws.

- 3** Connect the AC power cord.

#### Insertion of Connector

Even when the connector is perfectly inserted, depending on the type of inlet used, the front part of the connector may jut out as shown in the drawing.

However there is no problem using the unit.



- 4** Turn the MAIN POWER on.

- ① Press [PUSH OPEN] to open the cover panel.
- ② Press [MAIN POWER] button to select **ON**.  
 ( → )

MAIN POWER indicator lights up.

Charging of the battery starts.

The CHARGE indicator lights while the battery is charging and goes out when fully charged.

Now carry out the connections and operations on the following pages, leaving MAIN POWER ON to charge the battery.

#### Note

For your safety, POWER should be left standby until all other connections are complete.