



SCHEMATIC DIAGRAM



PURITY APPLY
R306 4.7K
C303 3300P/10K
R402 0.4K/5W



THE  SYMBOL MARK OF THIS SCHEMATIC DIAGRAM INCORPORATES SPECIAL FEATURES IMPORTANT FOR PROTECTION FROM X-RADIATION. FILTRATION AND ELECTRICAL SHOCK HAZARDS. WHEN SERVICING IT IS ESSENTIAL THAT ONLY MANUFACTURER SPECIFIED PARTS BE USED FOR THE CRITICAL COMPONENTS IN THE  SYMBOL MARK OF THE SCHEMATIC.			
COMPANY CONFIDENTIAL DO NOT COPY!			
DATE	2004.11.16	REV	01
MODEL	T930BUL	Sheet	1 / 1 Page

