

Chassis	Part Symbol	Defective Circuit	Symptom	solution
m134	None	System Control	Servicer installed replacement chassis but the parental lock was turned on, blocking all programming except for commercials. According to the customer instruction book the code was supposed to have been set to 0000. This wasn't the case.	Pressing the vol+ on the remote & ch+ on the FPA the password came up as 1111.
M134C	fpa	System Control	Connector (P001b) on replacement fpa is reversed. Set comes on as soon as you plug in, will not turn off and remote will not work.	reverse connector